

Appendix no. 3 Photographic documentation

The photos below show: the area before the Investment (left side) and after the Investment (right side).



*Phot. 1 View from powiat road no. 3233D to plot no. 242/5 before the investment (proposed demolition of existing foundations).*

Appendix no. 3 Photographic documentation



*Phot. 2 Gas pipeline running in north-south direction in the area of the reservoir bowl.*

Appendix no. 3 Photographic documentation



*Phot. 3 Section of powiat road no. 3233D running through the area of the right-bank abutment of the dam.*



*Phot. 4 View of the bottom outlet of the dam.*



*Phot. 5 View of the dam's technical maintenance building.*

Appendix no. 3 Photographic documentation



*Phot. 6 View of the dam and reservoir bowl.*