



CHECKING LIST ON IMPLEMENTATION OF MEASURES LISTED IN APPENDICES 1 AND 2 TO ENVIRONMENTAL MANAGEMENT PLAN

Appendix no. 1

to the Final Report on implementation of measures listed in the EMP for the period: 1 April 2019 – 25 December 2020

ODRA-VISTULA FLOOD MANAGEMENT PROJECT

Subcomponent OVFMP	3B Flood Protection of Sandomierz and Tarnobrzeg
Contract Task	3B.2 Flood Protection of Tarnobrzeg
Investor / Project Implementation Unit	State Water Holding Polish Waters Regional Water Management Authority in Rzeszów 17B. Hanasiewicza Street, 35-103 Rzeszów
Project Implementation Office (PIO)	State Water Holding Polish Waters Regional Water Management Authority in Rzeszów 17B. Hanasiewicza Street, 35-103 Rzeszów
Contractor	Joint-venture: Ekomel Sp. z o.o., Zakład Usług Wodno-Melioracyjnych i Rekultywacji Sp. j., DABI SM BUDNY Sp. z o.o. Sp.k.
Engineer	AECOM Polska Sp. z o.o. 34a Domaniewska Street, 02-672 Warsaw, Poland







This document, constituting **Appendix no. 1** to the *Final Report on implementation of measures listed in Environmental Management Plan for the Contract 3B.2* (reporting period: April 1, 2019 – December 25, 2020), prepared by the Engineer/Consultant, consists of the following 3 parts:

- Part I. Checking list on implementation of mitigation measures listed in Appendix 1 to the EMP for the Contract 3B.2
- Part II. Checking list on implementation of monitoring measures listed in Appendix 2 to the EMP for the Contract 3B.2
- Part III. List of quantitative summary of implementation of measures listed in Appendices 1 and 2 to the EMP during the reporting period.

Part I. Checking list on implementation of mitigation measures listed in Appendix 1 to the EMP for the Contract 3B.2

Explanations to checking list presented in Part I

Measures listed in Appendix 1 to the EMP for the Contract 3B.2 are divided into 9 categories (marked with letters *A - I*) and described in checking lists (*IN CAPITAL ITALIC FONT*):

Sign	Category	Item
A)	REQUIREMENTS CONCERNING ENVIRONMENTAL PROTECTION TO BE INCLUDED IN THE CONSTRUCTION DESIGN	1-8
В)	RULES CONNECTED WITH LAND ACQUISITION, ORGANIZATION OF THE SITE FACILITIES, WAREHOUSES AND STORAGE YARDS	9-27
<i>C</i>)	ADDITIONAL MITIGATION MEASURES CONCERNING THE RESTORING OF THE SHELTERS AND FEEDING SITES REFERRED TO IN THE ENVIRONMENTAL DECISION	28-30
D)	MEASURES TO BE IMPLEMENTED PRIOR TO THE COMMENCEMENT OF WORKS	31-46
E)	REQUIREMENTS CONCERNING ASSURANCE OF THE ACCESS ROUTES TO THE CONSTRUCTION SITE	47-57
F)	REQUIREMENTS FOR REMOVAL OF TREES AND SHRUBS	58-60
<i>G</i>)	REQUIREMENTS AT THE PERFORMANCE	61-111
<i>H</i>)	REQUIREMENTS AFTER COMPLETION OF THE WORKS	112-119
I)	GENERAL REQUIREMENTS	120

For each of the mitigation measures, the following was given:

- brief description of the measure (marked in *bold italic font*, together with a number in the "Item" column);
- exact description of the measure in the text of Appendix 1 to the EMP;
- description of the implementation status of the measure in the reporting period.

Table 1. Checking list on implementation of mitigation measures listed in Appendix 1 to the EMP for the Contract 3B.2

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period	
(1)	(2)	(3)	
A) – REQUIREMENTS CONCERNING ENVIRONMENTAL PROTECTION TO BE INCLUDED IN THE CONSTRUCTION DESIGN			
Agreements concerning environmental protection to application in the Construction Design	Construction design and any other technical documentation elaborated by the Contractor shall consider recommendations resulting from the issued environmental decision.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.	
2) Recommended environmentally friendly technical solutions	A vertical cut-off wall will be made in embankment water-side foot. This barrier will be linked with a geomembrane screen. The barrier will reach max. 10 m below the terrain level. This screen in the embankment water-side slope will be made of geomembrane anchored at the top at the embankment crest and in the bottom in the vertical cut-off wall.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was completed in the 3. quarter of 2019. No problems were found in the implementation of the measure.	
3) Recommended technical solutions	Parameters of the extended embankments: Section I: width of the embankment – approx. 3 m and approx. 5 m at a road section going along it, inclination of the embankment water-side slope – 1:2.5÷1:4.7 and the embankment water-side slope – 1:2.5÷1:2.7, ordinate of the embankment crest – 143.91÷145.90 m above sea level (linked to the existing embankment ordinate). Section II: width of the embankment crest – approx. 3 m and approx. 5 m at a road section going along it. inclination of the embankment water-side slope – 1:2.2÷1:4.2 and the embankment water-side slope – 1:2.5; ordinate of the embankment crest – 146.06÷147.79 m above sea level (linked to the existing embankment ordinate). Section III width of the embankment crest – approx. 3 m and approx. 5 m at a road section going along it. inclination of the embankment water-side slope – 1:2÷1:4 and the embankment water-side slope – 1:2÷1:3, ordinate of the embankment crest – 147.79÷148.24 m above sea level (linked to the existing embankment ordinate). Section San width of the embankment crest – 2.5÷4 m, inclination of the embankment water-side slope – 1:2.5÷1:4.1 and the embankment water-side slope – 1:2.6÷1:2.8; ordinate of the embankment crest – 145.90÷146.23 m (linked to the existing embankment ordinate).	COMPLETED The implementation of the measure started in the 3. quarter of 2020 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.	

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
4) Recommended environmentally friendly technical solutions / Section I (the land plot no. 2 precinct Witkowice)	There will be no "green route" at the section running through the "Wisła pod Zawichostem" Nature Reserve i.e. at the section with a length of approx. 300 m (at the land plot no. 2, within the precinct of Witkowice, in the Radomyśl nad Sanem Commune).	COMPLETED The implementation of the measure started in the 4. quarter of 2020 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
5) Recommended environmentally friendly technical solutions / Section I	At the modernized embankment ramps in Section I, apart from ramps at km 0+530 and 6+410, it is required to set up barriers aimed to limit free entry into the embanked area by unauthorized persons / entities but letting land owners to enter (drive into) it.	COMPLETED The implementation of the measure started in the 4. quarter of 2020 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
6) Recommended environmentally friendly technical solutions	In order to secure the flood-protection embankments against digging and burrowing animals, there will be a galvanized steel mesh placed from the base of the flood-protection embankment to the height of control water at the embankment water-side slope, at a depth of min. 0.2 m below the ground. This mesh will have the following parameters: — thickness of its wire: min. 2.5 mm, — maximum dimensions of its eyelet: 8 x 8 cm, — anchoring by means of steel bars in an amount of min. 1 pc. per 1m ² . This mesh will be mounted along the entire length of the embankments covered by the Works Contract.	COMPLETED The implementation of the measure started in the 4. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
7) Recommended environmentally friendly technical solutions	Any interference with watercourses/ditches is permitted only to a limited extent, i.e.: 1) watercourses are permitted to be reinforced only within the redeveloped embankments water-locks / their inlets / outlets, respectively, Section I: a) the embankment water-lock 1.1 at km 2+735 at the drainage ditch: — the inlet: reinforcement of the bottom with a stone cover and the slopes with meshstone mattresses at a length of up to 5 m and a bank-wall (river-bank band) made of fascine bunch at a length of up to 27 m, — the outlet: reinforcement of the bottom with a stone cover and of the slopes with a mesh-stone mattress at a length of up to 5 m and a bank-wall (river-bank band) made of fascine bunch at a length of up to 25 m, moreover, at its estuary into the reservoir, a stone cover is permitted at a length of approx. 3 m in order to protect the place of water discharge. b) the embankment water-lock 1.2 at km 4+093 at the drainage ditch: — the inlet: reinforcement of the slopes with mesh-stone mattresses at a length of up to 27 m and a stone cover at the bottom, — the outlet: reinforcement of the bottom with a stone cover and of the slopes with a mesh-stone mattress at a length of up to 28 m; moreover a bank-wall (river-bank band) made of fascine bunch at a length of up to 28 m; moreover a bank-wall (river-bank band) made of fascine bunch at a length of up to 35 m, c) the embankment water-lock 1.3 at km 6+206 at the Strachocka river:	COMPLETED The implementation of the measure started in the 4. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
	the inlet: reinforcement of the bottom	1-7
	with a stone cover and of the slopes with a	
	mesh-stone mattress at a length of up to 11	
	m; moreover a bank-wall (river-bank band)	
	made of fascine bunch at a length of up to 66	
	m, locally at the river meander (the left bank) reinforcement of the slope with mesh-	
	stone mattress at a length of up to 20 m,	
	- the outlet: reinforcement of the bottom	
	with a mesh-stone mattress at a length of up	
	to 4 m, then with a stone cover – at a length	
	of up to 6 m and of the slopes with a mesh-	
	stone mattress; moreover a bank-wall (river-	
	bank band) made of fascine bunch at a	
	length of up to 25 m. Section II:	
	a) the embankment water-lock 2.1 at km	
	0+055 at the drainage ditch:	
	 the inlet: reinforcement of the bottom 	
	with a stone cover at a length of up to 14 m	
	and of the slopes with mesh-stone	
	mattresses; moreover a bank-wall (river-	
	bank band) made of fascine bunch at a	
	length of up to 26 m,	
	- the outlet: reinforcement of the bottom	
	with a stone cover and of the slopes with a mesh-stone mattress at a length of up to 16	
	m; moreover a bank-wall (river-bank band)	
	made of fascine bunch at a length of up to	
	23 m,	
	b) the embankment water-lock 2.2 at km	
	2+178 at the drainage ditch:	
	- the inlet: reinforcement of the bottom	
	with a stone cover and of the slopes with a	
	mesh-stone mattress at a length of up to 17 m,	
	- the outlet: reinforcement of the bottom	
	with a stone cover and of the slopes with	
	mesh-stone mattresses at a length of up to 9	
	m; moreover a bank-wall (river-bank band)	
	made of fascine bunch at a length of up to	
	28 m, c) the embankment water-lock 2.3 at km -	
	4+887 at the Sanna river:	
	- the inlet: reinforcement of the bottom	
	with a stone cover and of the slopes with	
	mesh-stone mattresses at a length of up to 18	
	m and a bank-wall (river-bank band) made	
	of fascine bunch at a length of up to 48 m,	
	- the outlet: reinforcement of the bottom	
	with a stone cover and of the slopes with	
	mesh-stone mattresses at a length of up to 16 m; moreover a bank-wall (river-bank band)	
	made of fascine bunch at a length of up to	
	30 m,	
	Section III:	
	a) the embankment water-lock 3.1 at km	
	0+303 at the drainage ditch:	
	- the inlet: reinforcement of the bottom	
	with a stone cover at a length of up to 8 m	
	and of the slopes with a mesh-stone mattress - the left bank at a length of up to 31 m, the	
	right bank - at a length of up to 8 m, at the	
	remaining section - the left bank at a length	
	of up to 56 m, the right bank at a length of	
	,,	

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
	up to 76 m - a bank-wall (river-bank band) made of fascine bunch, — the outlet: reinforcement of the bottom with a stone cover and of the slopes - with mesh-stone mattresses at a length of up to 12 m and then the right bank: at a length of up to 107 m - a mesh-stone mattress, further 119 m - a bank-wall (river-bank band) (fascine bunch), the left bank at a length of up to 113 m - a bank-wall (river-bank band) (fascine bunch).	
8) Recommended environmentally friendly technical solutions	On the sections of the embankment, where cut-off wall is designed, the cut-off wall will be constructed using Deep Soil Mixing technology.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was completed in the 3. quarter of 2019. No problems were found in the implementation of the measure.
B) – RULES (CONNECTED WITH LAND ACQUISITION, ORG WAREHOUSES AND STORAC	
9) Illegal, or excessive land occupancy, which may cause losses with regard to archaeological, or natural resources and crops / The whole sections of the embankment being redeveloped	Any occupation of land beyond the project demarcation lines indicated on the Site Plan and obtained by the Contractor for the site facilities and storage yards is prohibited.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. In the 4. quarter of 2019 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
10) Real estate acquisition for permanent occupation/ The whole sections of the embankment being redeveloped	Buyouts, compensation and help for the Project Affected People (by Land Acquisition and Resettlement Action Plan).	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was completed in the 4. quarter of 2019. No problems were found in the implementation of the measure.
Real estate acquisition for temporary occupation/ The whole sections of the embankment being redeveloped	Payment of compensation by the Contractor for temporary occupation before commencement of works (by Land Acquisition and Resettlement Action Plan).	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
12) Environmental protection / Construction site facilities and storage places	The Contractor, by their own effort, will acquire an area for the site facilities and storage yards. Any approval for temporary occupancy must be preceded by an analysis of its impact on particular environmental elements. When selecting the location for the site facilities for the construction site, the Contractor will consider the following aspects: - examining the area for its ground base, vegetation and ground water table: any construction sites should be located on areas free from trees and where the ground water table is below 1.0 m b.g.l., - the geological structure of area of construction site location shall effectively protect ground water,	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
	 the construction site location shall provide convenient access to energy and water supply for social purposes. the access road to the site facilities shall not hinder access to the nearby buildings, locate the construction site only beyond the area of any protected habitats, it is not allowed to locate the site facilities within the terrace area. The Contractor should prepare construction site organization plan which will indicate, apart from the location of the construction site facilities, the conditions of its management, including: the location of parks for the construction equipment and other vehicles, the method of soil and water protection against contamination with substances harmful for the environment, the method of draining rainfall water, the location of the warehouses for construction materials, and the 	
13) Environmental protection / Construction site facilities and storage place(s)	Area of occupation must be limited to the necessary minimum as well as land surface transformation during the works carried out. Construction site facility(ies) and storage place(s) must be properly marked and the signs maintained in good condition throughout the whole duration of the works. The construction site facilities should be set up beyond the place of occurrence of wildlife habitats, i.e. within min. 30 m from the edge of a given valuable natural habitat (its panel). The selection of this place of the construction site facilities requires consultation with the Contractor's environmental team and Engineer's approval. It is permitted to locate material bases at the following locations: A. Section I: a) main: at km 0+550÷0+750 (at the land-side), at km 1+750÷2+500 (at the land-side), at km 7+000÷7+200 (at the land-side), at km 7+000÷7+200 (at the land-side), at km 0+000÷0+550 (at the land-side), at km 2+500÷2+700 (at the land-side), at km 2+870÷2+850 (at the land-side), at km 2+870÷2+850 (at the land-side), at km 2+870÷7+000 (at the land-side), at km 2+870÷7+000 (at the land-side), at km 0+000÷0+150 (at the land-side), at km 0+000÷1+600 (at the land-side), at km 1+850÷2+200 (at the land-side), at km 1+850÷2+200 (at the land-side), at km 2+500÷2+700 (at the land-side), at km 1+850÷2+200 (at the land-side), at km 1+850÷2+200 (at the land-side), at km 2+500÷2+700 (at the land-side), at km 4+850÷2+200 (at the land-side), at km 2+500÷2+700 (at the land-side), at km 4+1700÷1+800 (at the land-side), at km 4+1700÷1+800 (at the land-side), at km 4+180÷2+200 (at the land-side), at km 4+180÷3+200 (at the land-side), at km 4+180÷4+250 (at the land-side), at km 4+180÷4+850 (at the land-side), at km 4+450÷4+850 (at the land-side),	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. In the 4. quarter of 2019 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
	a) main: - at km 0+050÷0+350 (at the land-side), - at km 0+800÷1+000 (at the land-side), - at km 1+300÷1+500 (at the land-side), b) potential - at km 0+350÷0+800 (at the land-side). In the first place the location of material bases will affect the areas specified above as the main ones.	
14) General principles for carrying out works / The whole sections of the embankment	Order should be maintained on the Site as well as proper works' management.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
15) General principles for carrying out works / The whole sections of the embankment	The Contractor shall ensure constant visibility conditions during the day and at night of such structures and signs which are obligatory for safety reasons.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
16) Environmental protection / Construction site facilities and storage places	All storage places of bulk materials will be secured against its dispelling and dissolving (e.g. by means of tarpaulins).	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
17) Environmental protection / Construction site facilities and storage places	Stored materials should be so formed and stored, in order to limit the formation of so-called ecological traps e.g. in the form of short-term favorable conditions for nesting.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
18) Environmental protection / Construction site facilities and storage places	All storage places of construction materials and/or waste will be set up beyond the special flood hazard area.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. From the 1. quarter of 2020 until the 4. quarter of 2020 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
19) Environmental protection / Construction site facilities and storage places	The risk of water contamination by operational fluids derived from vehicles and machines will be mitigated by running regular checks on the technical condition of equipment and provision of sorbents (aimed to neutralize leaks) at the construction site.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. In the 2. quarter of 2020 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
20) Environmental protection / Construction site facilities and storage places	The construction site facilities should be located at places which allows for the delivery of materials which require periodic storage prior their use at the construction site. Access roads to the construction site should be lined with concrete slabs, which - upon the completion of works - will be removed.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
21) Water and soil protection / Construction site facilities	The construction site facility/item will be equipped with portable toilets (being provided with features to collect wastewaters by companies with appropriate entitlements to conduct this type of activity). The wastewaters will be transported to the nearest sewage treatment plant or catchment area.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
22) Water and soil protection / The whole sections of the embankment	It is prohibited to store waste, ground masses and set up construction site facilities and material bases within the embanked area of the Vistula river, hollows and areas of water stagnation, wetland depressions as well as within other habitats specified by the Contractor's environmental team.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. Throughout the entire reporting period problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
23) Trees protection / The whole sections of the embankment with growing trees and shrubs	It is prohibited to gather any construction materials and waste near tree trunks (i.e. within the contour of tree crests and at least 2 m beyond this contour) and shrubs.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. In the 1., 3. and 4. quarter of 2020 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
24) General principles for carrying out works / The whole sections of the embankment	The manner of materials storage or topsoil management must not change the water levels with detriment to the neighbouring soil.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
25) Environmental protection / Construction site facilities and storage places	If hazardous substances and materials are stored on the building site, they must be protected appropriately, preventing the access of unauthorized persons, and information on a hazard must be provided on warning boards.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
26) Environmental protection / Construction site facilities and storage places	Solid waste management must be carried out in accordance with the Act of 14 December 2012 on waste. It is required to follow a rule of minimizing the amount of the waste generated. Waste generated during the Task implementation must be segregated and collected in containers or dedicated places, ensuring protection against the leakage of hazardous substances and it is necessary to ensure successive collection of waste by authorized entities.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. From the 4. quarter of 2019 until the 4. quarter of 2020 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
27) Environmental protection / Construction site facilities and storage places	Hazardous waste to be collected only by authorized entities. Until the waste is collected by authorized entities it must be stored in a way which prevents penetration of the hazardous substance to the environment, i.e. in sealed containers, in roofed areas, on paved surface, protected from unauthorized access.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
C) – ADDITION	AL MITIGATION MEASURES CONCERNING T FEEDING SITES REFERRED TO IN THE ENV	
28) Mitigation of negative impacts / Outside the area of works	Nesting booths should be hung out before works commencement: a) the total number - 280, including: 105 - type "A", 150 - type "B", 6 - type "D" for hoopoe, 9 - for mergansers and owls, 2 - for nuthatch, 8 - for kestrels, b) at least half of these booths will be hung out within Section II, c) works related to the hang-out of nesting booths for birds should be conducted under the supervision of the Contractor's ornithologist with the record of their location in the GPS system and at the map, d) these boxes will be regularly (annually) maintained and cleaned in autumn and winter periods (removal of old nests - in the period from 16 October to the end of February). Such maintenance and cleaning of the existing boxes will be run for a period of 10 years from the start of construction works and of new boxes - for 10 years upon their set-up. Appropriate permits should be obtained for the above-mentioned activities to be conducted within the nature reserve area.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was completed in the 1. quarter of 2020. After the works completion the implementation of the measure within the Defect Notification Period and Warranty Period has been planned. In the 2. quarter of 2019 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
29) Mitigation of negative impacts / Outside the area of works	Before works commencement it is required to hang out boxes for bats in the number of 50 along the entire section of performance of these works, in the embanked area at places specified and supervised by the Contractor's chiropterologist. These boxes will be made from sawdust, wood or other material in accordance with the current environmental knowledge and guidelines provided by the Contractor's chiropterologic expert. Breeding boxes will be hung at trees at a height of over 4 meters, at a distance of not less than 50 meters from one another on the western or southern side of their trunks. These boxes will be arranged in tree clusters in the embanked area, more or less evenly, in sunny places which border with tree plantings. Their exact locations must be fitted to terrain and habitat conditions taking into account access (convenient access road / path) at their installation and monitoring. When hanging these breeding boxes it is necessary to mark their positions (via the GPS system) and draw up a map of their locations. It is possible to place them close to the embankment, which allows for their hang-out.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was completed in the 1. quarter of 2020. After the works completion the implementation of the measure within the Defect Notification Period and Warranty Period has been planned. In the 2. quarter of 2019 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
30) Mitigation of negative impacts / Outside the area of works on the indicated sections	Before works commencement it is necessary to mount 25 poles with a height of 120-180 cm, with planting of wild rose and/or hawthorn bushes (with a height of 50-80 cm, having at least three shoots), in order to create favorable habitats for red-backed shrike. These poles will be arranged at a distance of 300 meters from one another, on the eastern side of the embankments, at a distance of 20 - 30 meters from them (so as not to interfere with their infrastructure and mowing). Such poles with rose bushes and/or hawthorn bushes should be placed in open areas for: Section II: 0+000÷2+000 km of the embankment, Section I: 5+800÷7+100; 3+600÷4+300 and 0+000÷2+500 km of the embankment. During the vegetative period, the planting of shrubs should be weeded twice a year. The above-specified works will be performed under the supervision of the Contractor's ornithologist and the Contractor's botanist.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. After the works completion the implementation of the measure within the Defect Notification Period and Warranty Period has been planned. In the 2. quarter of 2019 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
D) - MI	EASURES TO BE IMPLEMENTED PRIOR TO T	HE COMMENCEMENT OF WORKS
31) Land surface and landscape protection, habitat protection / The whole sections of the embankment being redeveloped	Prior to conducting earthworks, it is necessary to remove a fertile layer of soil with its thickness of 20 - 30 cm, which is then to be stacked at the behind-embankment, cared and used to clear the area upon the completion of construction works and top-soiling. The fertile layer of soil will be removed beyond the period from 1 March to 31 July. At wetlands, within which the Contractor's environmental team reports the habitat of amphibians, it will be conducted in the period from 1 August to 15 October. If - due to technical reasons - it is necessary to conduct the works (thoroughly or partially) at another time it will be performed under supervision of the Contractor's environmental team.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was completed in the 3. quarter of 2020. In the 2., 3. and 4. quarter of 2019 and in the 1. and 3. quarter of 2020 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
32) Habitats protection / Neighborhood of redeveloped embankment	All valuable natural habitats pointed out by the Contractor's environmental team (e.g. alluvial forests, plant clusters to be protected etc.) in the proximity of which works will be conducted will be properly protected during works by means of a forest net.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
33) Habitats protection / Neighborhood of redeveloped embankment	Within the boundaries of the "Wisła pod Zawichostem" Nature Reserve, before the start of construction work, the forest area should be enclosed, at least by means of a forest net.	COMPLETED The implementation of the measure started and was completed in the 1. quarter of 2020. No problems were found in the implementation of the measure.
34) Habitats protection / Section I km 3+020÷3+310	Prior to the start of construction works, the boundaries of the "Wisła pod Zawichostem" Nature Reserve will be marked by means of 35 boards with the following text: "Rezerwat przyrody Wisła pod Zawichostem" [Vistula at Zawichost Nature Reserve] made of galvanized steel sheet. Each of them will be placed on a galvanized steel post (with a diameter of at least 60 mm and a wall thickness of at least 3 mm) fixed permanently to the ground. The boards will be executed in accordance with the Regulation of the Minister of Environment dated 10 December 2004 on the design of plates (Journal of Laws No. 268, item 2665).	COMPLETED The implementation of the measure started and was completed in the 1. quarter of 2020. No problems were found in the implementation of the measure.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
35) Buildings protection / Surrounding of the redeveloped embankment in places where there are nearby buildings	The existing buildings and structures adjacent to the construction site and those which may be affected by construction work carried out by the Contractor should be inventoried prior to the commencement of works.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was completed in the 4. quarter of 2019. No problems were found in the implementation of the measure.
36) Trees and shrubs protection / The whole sections of the embankment with growing trees and shrubs	Trees and shrubs not intended for felling, located close to the places where the works will be carried out, should be protected. The following trunk covers will be applied e.g. such as straw mats, formwork made of braided wired boards (trimmed boards, 2nd class, min. thickness - 20 mm, round galvanized steel wire), soil used to backfill boards at the base of tree trunks. In case the above protective measures cannot be technically applied, it is recommended to enclose (for the duration of the work) groups of tree / shrub plantings. Wooden bars having a diameter of approx. 6 cm and a height of approx. 2.5 m, polypropylene mesh with a height of approx. 1.8 m in bright colors, galvanized wire will be used among others to secure greenery; in case this is not technically plausible, fencing will be made by means of a colored tape. If any trunk cover is destroyed or stolen, the Contractor shall promptly replace it or supplement it. When works are completed at a given section, the above-specified protective measures will be removed.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
37) General conditions concerning nature protection - prevent and elimination of invasive species / The whole sections of the embankment	Prior to beginning of the construction works carry out field inspection of place of works with participation of Contractor's botanist in order to locate the presence and estimate population of invasive plants. After locating and visibly marking in places where invasive plants grow take preventive actions during the implementation investment, which limit spreading of these plants, including, among others, removing topsoil layer along with invasive plants and transporting them from area of works to the composting plant or neutralizing in any other effective manner. It is unacceptable to mix this topsoil with topsoil overgrown with local native vegetation.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was completed in the 2. quarter of 2020. No problems were found in the implementation of the measure.
38) Accidents of local inhabitants caused by vehicle and machine traffic / The whole sections of the embankment	Proper demarcation of construction area and the access roads. The Contractor's Work Safety supervision will be responsible for proper marking of the Construction Site in accordance with relevant regulations. This signage will be regularly controlled and if any signage is destroyed or stolen, the Contractor shall promptly replace it. The access roads will be marked in accordance with relevant regulations and agreement with the Administrators of the roads used by the Contractor. This signage will be regularly controlled, if any signage is destroyed or stolen, the Contractor shall promptly replace it.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. In the 3. quarter of 2020 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
39) Employee accidents during works/ The whole sections of the embankment	Preparation, implementation and compliance with the Health and Safety Protection Plan by the Contractor.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was completed in the 2. quarter of 2020. No problems were found in the implementation of the measure.
40) General principles for carrying out works / The whole sections of the embankment	The Contractor shall ensure the preparation, implementation after the approval by the Engineer of Building site organization design.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
41) General principles for carrying out works / The whole sections of the embankment	The Contractor shall ensure the preparation, implementation after the approval by the Engineer of Quality assurance plan.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
42) Fauna protection / The indicated sections of the embankment	In order to secure the construction site against the potential entry of amphibians into the area, prior to starting construction works, protective fences will be placed within sections pointed out by the Contractor's herpetologist. These fences will be made full (e.g. using film) or perforated (e.g. using mesh, with their maximum mesh size of 4.5 to 4.5 mm) and is buried down to a minimum depth of 15-20 cm. The height of aboveground fencing, throughout its length, will be at least 50 cm above ground level. The upper edge of fencing will be smoothly finished and bent outwardly, throughout its length, at an angle of 45-90° forming a peak with minimum width of 10 cm. This protective fencing - during the activity of amphibians - will regularly (at least once a week) checked for leaks. Any defects will be eliminated on a regular basis. Vegetation along these protective fences will be mowed. At the ends of this protective fencing, it is necessary to dig out pits with their dimensions of approx. 0.5 x 0.5 x 0.2 m, which will be lined with little buckets with more or less the same dimensions can be tightly dug). Twice a day: in the morning and evening - during the activity of amphibians - the Contractor's herpetologist will collect amphibians gathering along the fencing as well as found in buckets and transported them to their replacement position. It is advisable to place, for example, sticks in buckets in order to let small mammals leave them. Upon the period of activity of amphibians such pits and buckets will be removed.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
43) Fauna protection / The indicated sections of the embankment	Works conducted at spring mass migration places for amphibians identified by the Contractor's herpetologist will be made within a landline (with its width corresponding to the width of the migration corridor) with the exception of the period from 1 March to 31 May, i.e. upon the end of the main period of breeding migrations of this group of animals. These temporary enclosures of the above-mentioned corridors are designed to allow amphibians to reach their mating places and reduce their mortality (being run over by mechanical equipment). Fences - as recommended by the Contractor's herpetologist also used in the	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
	period of autumn migrations in order to protect individuals moving to their wintering grounds. Fences will be placed within the following mileage: A. Section I: a) at km 2+200÷2+350 (at the water-side), b) at km 2+600÷2+800 (at the water-side), c) at km 2+750÷2+850 (at the land-side) and within a length of approx. 150 m on the right side of the access road at km 4 + 100 of the embankment, e) at km 5+600÷5+700 (at the water-side), g) at km 6+150÷6+230 (at the water-side), at km 6+150÷6+230 (at the water-side), i) at km 6+150÷6+230 (at the water-side), i) at km 6+150÷6+230 (at the water-side), i) at km 6+150÷6+250 (at the water-side), ii) at km 6+150÷6+250 (at the water-side), j) at km 6+650÷7+000 (at the land-side) and within a length of approx. 100 m along the right side of the local access road (which allows to reach the embankment) located at km around 1+600, C. Section II a) at km 0+000÷0+100 (at the water-side), at km 0+920÷1+150 (at the water-side), at km 1+950÷2+100 (at the land-side), d) at km 1+950÷2+100 (at the land-side), i) at km 2+250÷2+050 (at the water-side), i) at km 2+850÷3+150 (at the water-side), i) at km 3+150÷3+300 (at the water-side), i) at km 3+150÷3+300 (at the water-side), i) at km 3+150÷3+300 (at the water-side), i) at km 4+700÷5+000 (at the land-side) together with the double-sided fencing local of the local access road (which allows to reach the embankment) (at km around 4+900) within a length of approx. 100 m D. Section III a) at km 0+450÷50 (at the land-side), together with the double-sided fencing local of the local access road (which allows to reach the embankment) (at km around 4+900) within a length of approx. 100 m D. Section III a) at km 1+300÷1+720 (at the land-side), of the local access road (which allows to reach the embankment) (at km around 4+900) within a length of approx. 100 m D. Section III a) at km 1+300÷1+720 (at the land-side), of the local access road (which allows to reach the embankment) (at km around 4+900) within a length of approx. 100 m D. Section III	reporting period
	justified, the above-mentioned fences may be placed also at other sections specified by the Contractor's herpetologist. The design of these enclosures was specified in item 42.	
44) Protection of monument / Section II km 4+880 of the embankment	In km 4+880 of the embankment of the Vistula River (Section II, plot no. 1714/3, precinct Wrzawy) in the area of works impact there is a memorial site (mound with monument, around the monument is located the area of the old war cemetery of 1809). The Contractor's obligation shall be the protection of the memorial site for the period of works performance so that no damage of the object occurs as a result of the Investment realization.	NOT APPLICABLE There was no need to implement the measure in the reporting period (no impact of the construction works and the construction site zones on the memorial site referred to in item 44 of the Appendix 1 to EMP).

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
45) Protection of memorial stone / Section I km 6+400 of the embankment	In km 6+400 of the embankment of the Vistula River (Section I, plot no. 203/3 precinct Witkowice) in the area of works impact there is a stone with commemorative plaque (thanks for involvement of the local community in the fight against flood) founded in 2005. The Contractor's obligation shall be the protection of the stone for the period of works performance so that no damage of the object occurs as a result of the Investment realization.	COMPLETED The implementation of the measure started in the 4. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
46) Control of the settlement and protection of the building to be demolished / Section II, land plot No. 975 precinct Wrzawy	On the land plot no. 975 precinct Wrzawy, there is an abandoned residential building intended for demolition. This building should be inspected by the Contractor's ornithologist and Contractor's chiropterologist for bird and bat occupation. In case of settlement, take steps recommended by these experts to allow birds and bats to leave this shelter / nesting place and then secure the building against re-colonization until its demolition.	COMPLETED The implementation of the measure started and was completed in the 2. quarter of 2019. No problems were found in the implementation of the measure.
E) - REQUIREME	NTS CONCERNING ASSURANCE OF THE ACC	ESS ROUTES TO THE CONSTRUCTION SITE
47) Natural resource protection / Embankment sections where existing roads are located that the Contractor will use	Transport of construction materials, aggregates and waste, as well as traffic of machines and vehicles shall be conducted on existing roads or designated temporary roads, established in such a way so as to reduce interfering with the habitat identified by the Contractor's botanist.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
48) Noise protection / The whole sections of the embankment	Any activities related to transport of construction materials, aggregates and waste by trucks at the stage of Works Contract implementation shall be conducted only during the day i.e. from 06.00am to 10.00pm only.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
49) Natural resource protection / sections of embankment, where existing roads will be used by Contractor	The access roads used for vehicle transport of materials should be maintained in good technical condition, and after the completion of construction works will be restored to a state not worse than before the implementation of the Works Contract. The Contractor will also be responsible for maintenance of exit routes in good technical condition.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
50) Natural resource protection / sections of embankment, where existing roads will be used by Contractor	During works performance the Contractor makes efforts to minimize the burdens for the vehicle traffic existing in the works area.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. From the 1. quarter of 2020 until the end of the reporting period problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
51) Natural resource protection / Embankment sections where existing roads are located that the Contractor will use	Parking of cars of the Contractor's employees may take place only in a designated area. It is prohibited to park in the area of habitats.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. From the 4. quarter of 2020 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
52) Protection of social interests / The whole sections of the embankment being redeveloped, surrounding	The Contractor is obliged to provide photographs of the whole work area along with access roads and their surroundings with particular focus on the technical condition of the roads and buildings located in the vicinity of any roads used for transport of building materials. Before commencing the works, the Contractor shall carry out, with the Administrator present, an inspection in the area on the basis of which a report shall be prepared on the condition of the roads prior to access for construction purpose. Based on that, the Contractor will be obliged to restore their technical condition.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
53) Protection of social interests / Embankment sections where existing roads are located that the Contractor will use, and where temporary routes will be designated	It is required to ensure human protection against increased vehicle traffic along roads used during construction works. At the time of works execution, the Contractor shall supply, install and operate all temporary safety devices, ensuring the safety of vehicles and pedestrians.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
54) Protection of social interests / Embankment sections where existing roads are located that the Contractor will use, and where temporary routes will be designated	The vehicle traffic should take place on the service roads preventing any damage to the nearby vegetation.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
55) Protection of social interests / The whole sections of the embankment being redeveloped, surrounding	The Contractor shall be responsible for any damage to the structures, buildings, roads, drainage ditches, culverts, water supply and gas pipe lines, power poles and power lines, cables, land survey control network and any type of services as well as other types of facilities such as vertical and horizontal signs, information boards, cultural assets etc., caused by the Contractor or his Subcontractors during execution of works. The Contractor is also responsible for restoring the flow capacity of drainage ditches and drainage services in the area of conducted works and transport roads, in case of damage caused by execution of works and transport related to works implementation. The Contractor shall immediately repair any damage at his own expense and also, if necessary, shall perform other works ordered by the Engineer.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
56) Protection of social interests / Embankment sections where existing roads are located that the Contractor will use, and where temporary routes will be designated	The Contractor is obliged to agree with road management authorities of the traffic arrangement and works security plan. The Contractor is obliged to organize traffic in accordance with the agreed plans (marking and securing the Site and marking of de-tours and recommended road signage related to change of traffic organization, etc.).	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period	
(1)	(2)	(3)	
57) Protection of social interests / Embankment sections where existing roads are located that the Contractor will use, and where temporary routes will be designated	The Contractor shall respect the statutory limitations of speed and loads per vehicle axle during transport of materials and equipment to and from the construction site. The Contractor shall also obtain any necessary permits from authorities, for transport of non-standard loads and shall constantly inform the Engineer about each case of such a transport.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.	
	F) - REQUIREMENTS FOR REMOVAL OF	TREES AND SHRUBS	
58) Tree protection, bird protection / The whole sections of the embankment	The felling of approx. 2910 trees and shrubs with its area of approx. 3.12 ha will be limited to the area within the project demarcation lines. Moreover, this felling will be conducted within the period from 16 October to 15 February.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was completed in the 1. quarter of 2020. No problems were found in the implementation of the measure.	
59) Fauna protection / The whole sections of the embankment	In case of intention of cutting trees with their breast height above 50cm, perform with the participation of Contractor's specialists: - entomologist - control of the trees for occupancy by the protected beetle species, - chiropterologist - control for occupancy bats presence control. In case when the presence of beetles is established (larval or adult forms), permission for felling trees can be conditioned only by technical or process conditions after obtaining by the Contractor - as required by law - the permit from the competent authority to destroy habitat of protected species (in co-operation with entomologists) where appropriately-cut fragments of trees will be moved, (according to the NEPA, Act from 16 April 2004 - article 56). In case of observing the presence of bats in trees to be cut, suspend cutting temporarily and implement the Contractor chiropterologist's recommendations which are adequate to the current atmospheric conditions and the identified species of bats.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was completed in the 1. quarter of 2020. No problems were found in the implementation of the measure.	
60) Invertebrate protection / The whole sections of the embankment	In case, valuable species of saproxylobionts (including, among others: Hermit beetle) are found within trees projected for removal, it is necessary to take out rotten wood with them at their larval or other preimaginal stages and transfer them to another tree (with visible wood depreciation) located nearby. These works will be performed under the supervision of the Contractor's entomologist after obtaining by the Contractor a respective permit of RDOŚ/GDOŚ (according to NEPA - Art. 56 of the Act of 16 April 2004).	NOT APPLICABLE There was no need to implement the measure in the reporting period (no saproxylobionts were found within trees projected for removal referred to in item 60 of the Appendix 1 to EMP).	
	G) - REQUIREMENTS AT THE PERFORMANCE		
61) General principles for carrying out works / The whole sections of the embankment	Flood Management Plan should be provided for the duration of construction works, specifying the relation between the time of commencement of the evacuation or protection of the equipment and the occurrence of a certain hydro-meteorological situation. This plan must be approved by the Engineer.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.	

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
62) General principles for carrying out works / The whole sections of the embankment	Construction works should be conducted outside the flood risk season. The Contractor will be obliged to establish communication with IMGW-PIB to receive current information on weather forecast. In case of any warning about high water, the Contractor shall immediately notify the Engineer and the Employer and shall take appropriate actions according to the procedures described by the Flood Management Plan.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
63) Land surface and landscape protection, habitat protection / Embanked area	Ground masses required to accomplish the Investment will come from external or internal (in case when the Contractor has his own mine) suppliers; it is not projected to collect ground from within the embanked area. It is concluded on the basis of the EIA Report that within 20 km from the projected Investment there are several aggregate mines which can provide necessary ground masses with specified parameters. Then supplies of ground masses may run independently, which is its key advantage.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
64) Contractor's environmental supervision team / The whole sections of the embankment	The construction works realized by the Contractor will be conducted under the supervision of an experienced Contractor's environmental team: a) team will be composed of ornithologist, botanist, herpetologist, entomologist and chiropterologist; this Contractor's environmental supervision will be performed by specialists with higher education in the field of biology, forestry, environmental protection who has run at least two professional wildlife supervisions during investments in the field of ornithology / botany / herpetology etc., respectively (in case a given specialist has experience in the field of for example botany and herpetology it is possible to combine these two functions by one person); b) The Coordinator / Team Leader of the environmental team will be appointed; c) throughout the duration of the investment the Contractor's environmental team will oversaw the observance of the terms and conditions of the EMP and the environmental decision.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
65) General principles for carrying out works / The whole sections of the embankment and surrounding	The Contractor should provide the schedule for execution of works so that the dates and location of respective stages of construction works are in compliance with requirements of environmental decisions and EMP and so that they do not have negative impact on species under protection which are found on the Investment implementation area and in its vicinity.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
66) Trees and shrubs protection, Nature protection / The whole sections of the embankment and surrounding with growing trees and shrubs	It is unacceptable to damage trees and shrubs which are not intended for felling and near which earthworks related to the Works Contract are conducted. During construction works it is also not allowed to destroy plants outside the Contract area.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
67) Trees and shrubs protection / The whole sections of the embankment with growing trees and shrubs	Fungicides will be applied to protect wounds of trees and shrubs after technical cuts and for potential maintenance of greenery damaged during the execution of works.	COMPLETED The implementation of the measure started in the 4. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
68) Employee accidents during works/ The whole sections of the embankment	Work of machinery and equipment within the embankment must be carried out in a way that does not endanger the safety of persons and property, excluding their overturning, sliding or descent into the slope of the embankment. Machinery and tools must be used according to their intended use.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
69) General principles for carrying out works / The whole sections of the embankment	No repairs and maintenance of facilities and equipment (e.g. oil replacement etc.) will be conducted at the construction site. The places where the machines are to be refueled must be equipped with the appropriate amount of sorbent. Workers must be trained how to deal with contamination of soil or water.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
70) Environmental protection / The whole sections of the embankment	In the course of the Works Contract no works may interfere in the Vistula riverbed and its riverside vegetation; then their interference into the embanked area will be limited to its marginal side which is directly adjacent to the planned embankment. The Works Contract will be limited to the area directly occupied for the Investment i.e. the redeveloped section of the embankment with a technological landline margin within its demarcation lines and the construction site facilities area.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
71) Habitats protection / watercourses on the whole sections of the embankment	Any works interfering with watercourses, ditches and their beds should be performed beyond the period from March 1 to June 30 and conducted from their bank positions.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
72) Environmental protection / The whole sections of the embankment	All earthworks should be conducted at riverside positions, first from one river bank and then from the other, in the way which ensures keeping the base flow.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
73) Environmental protection / The whole sections of the embankment	Drainage water from construction trenches, prior to their introduction into the environment, should be cleaned (due to the high content of total suspension).	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
74) Ornithofauna protection / section from the estuary of the San river downstream to the village of Zawichost	The section from the estuary of the San river downstream to the village of Zawichost will be completely excluded from works in the period from April 1 to the end of June. At this section heavy construction works i.e. earthworks conducted with the use of heavy construction equipment, transport and storage of the ground masses will be performed in the period from 1 August to the end of January. Lighter works i.e. clean-up works without the use of heavy construction equipment and high-capacity trucks may be used throughout the year except for the period from April to June.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
75) Ornithofauna protection / the Strachocka river basin	It is prohibited to eliminate reeds at the Strachocka river and any interference into them. No construction works will be conducted by the Contractor in the period from 1 April to 31 July within a distance of less than 50 meters from them.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
76) Fauna protection / The whole sections of the embankment	Works interfering into breeding sites for amphibians identified by the Contractor's herpetologist (e.g. water reservoirs, drainage ditches, drains from embankment water locks, places of periodic water stagnation) will be conducted beyond the period from 1 March to 30 June, then works interfering into wintering places for amphibians identified by the Contractor's herpetologist will be conducted with the exception of the period from 1 November to end of February. Works interfering with breeding and wintering sites for amphibians should be performed in the period from 1 July to the end of October.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
77) Fauna protection / The whole sections of the embankment	Wheel tracks and other ground depressions (emerged at the construction site) where water can be collected will be immediately eliminated in order to prevent amphibians from their spawn deposition and settlement at these places. All amphibian habitat which will emerge at the construction site i.e. deep trenches with stagnant water, deep wheel tracks, will be - prior to their backfilling - checked for the presence of amphibians. In case any amphibians are found, it is necessary to drain water and - upon lowering the water level - penetrate the bottom and catch animals under the Contractor's herpetological supervision. Any caught animals should transferred to appropriate (for individual species) habitats. Dried trenches, wheel tracks should be backfilled just after these animals are caught, in the presence of the Contractor's herpetologist.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
78) Fauna protection / The whole sections of the embankment	Wetlands, which are the habitat of amphibians, prior to their elimination should be checked by the Contractor's herpetological supervision for the presence of animals. Wetlands will be eliminated under the Contractor's herpetological supervision. Works will be conducted in September. Any caught animals should transferred to their - appropriate for individual species - habitats. In case it is necessary to destruct habitats which are wintering places for amphibians, at the beginning of September for the duration of works, these habitats should be enclosed in order to restrict access to them by winter migratory birds.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
79) Contractor's environmental supervision team / The whole sections of the embankment	Contractor's herpetological supervision - along the entire section of the conducted works - will catch the amphibians - catchments (from taps) should continue throughout the activity of amphibians; caught amphibians will be transferred to their suitable habits located beyond the construction site as selected by the Contractor's herpetological supervision; In case of amphibians migrated for breeding "in amplexus", they will be transferred in pairs; amphibians should preferably be transferred with soft water plants, moss or leaves, preferably in humid conditions than in water; if this transfer occurs in water, its amount has to be adapted to its individuals and their sizes.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
80) Fauna protection / The whole sections of the embankment	Trenches and structures which can be a trap for small animals, mostly amphibians, should be appropriately secured by the Contractor (e.g. tightly cover after day's works). Moreover, the above-mentioned places will be checked daily by the Contractor and, in case of any animals trapped in them, they will be caught and transferred to their - appropriate for given species - habitats beyond the area of works.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
81) Fauna protection / The whole sections of the embankment	Throughout the duration of the investment the Contractor's environmental team will oversaw the observance of detection and identification of animal species within the area of construction works and will prepared application for derogation decisions in case of protected species (according to NEPA - Art. 56 item 1 and 2 of the Act of 16 April 2004).	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
82) Flora protection / The whole sections of the embankment	Throughout the duration of the investment the Contractor's environmental team will oversaw the observance of detection and identification of plant species within the area of construction works and will prepared application for derogation decisions in case of protected species (according to NEPA - Art. 56 item 1 and 2 of the Act of 16 April 2004). If let by technical conditions, specimens of protected species will be transferred by the Contractor to their suitable habitats.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
83) Fungi protection / The whole sections of the embankment	Throughout the duration of the investment the Contractor's environmental team will oversaw the observance of detection and identification of fungi species within the area of construction works. In case of identifying specimen of any protected plants – after obtaining a respective permit of relevant nature protection authority (according to NEPA - Art. 56 of the Act of 16 April 2004) – transfer them to a habitat that fits a particular species beyond the work area. The botanist will indicate optimal technology and the site for replanting.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
84) Contractor's environmental supervision team / The whole sections of the embankment	Within the framework of the Contractor's environmental supervision it is indicated at least 8 visits per months are recommended under the wildlife supervision; upon every visit, there will be a description on the state, conditions and possible indications for the contractor together with by photographic documentation drawn up in the form of Control Data Sheet for Implementation of Mitigation Measures.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
85) Contractor's environmental supervision team / The whole sections of the embankment	The Contractor's herpetological supervision will be conducted on a continuous basis during the spring and autumn migration of amphibians; upon every visit, there will be a description on the state, conditions and possible indications for the contractor together with by photographic documentation drawn up in the form of Control Data Sheet for Implementation of Mitigation Measures.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
86) Noise protection / The whole sections of the embankment	The construction works related to the Works Contract implementation will be conducted daytime i.e. from 06.00 a.m. to 10.00 p.m. only.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
87) Noise protection / The whole sections of the embankment	At the stage of performance of construction works, the following technical and organizational measures should be applied: keep machines which emit noise and vibrations during the Works Contract implementation in good conditions which will allow for the observance of the standards set out in the applicable detailed regulations.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
88) Noise protection / The whole sections of the embankment	In order to reduce a level of noise emitted to the environment during construction works conducted close to the existing farm buildings and single family houses i.e. acoustic areas protected (allowed noise values are respectively $L_{\text{Aeqd}} = 55 \text{ dB}$ for a farm building and $L_{\text{Aeqd}} = 50 \text{ dB}$ for single family house for 8 the worst hours during the day), it is necessary to use portable sound barriers with their height of min. 4.0 m (applies to farm buildings located near redeveloped embankment of the Sections I÷III - distance from the building about 10 m to the border of the site and single-family housing development located near the embankment of section III - distance to the building about 70 m).	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
89) Noise protection / The whole sections of the embankment	In the areas under acoustic protection and the working sites adjacent to these areas, in order to mitigate the nuisance for inhabitants and environment, it is allowed to use only pumping engines equipped with soundproof housing.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
90) General principles for carrying out works / The whole sections of the embankment	In case of conducting construction works which cause the transmission of vibration exceeding the acceptable standards, appropriate methods aimed to reduce nuisance should be undertaken (in particular in respect to residential premises close to the embankments in the field of their technical security and comfort for sanitary maintenance and use).	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
91) Air protection / The whole sections of the embankment	It is required to seek to minimize the environmental impact of the Works Contract during its implementation through elimination of idling operation of combustion engines of machinery and transport equipment, among others during stops, breaks, etc.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
92) Water and soil protection / The whole sections of the embankment	Equipment, plant and vehicles used for construction works must be placed in dedicated parking spaces provided with protective measures against spillage of oil derivatives to the soil and water environment. If the equipment, plant and vehicles are not in use, they must be parked in these dedicated places.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
93) Water and soil protection / The whole sections of the embankment	Waste generated during the Works Contract implementation will be stored separately in containers at the construction site facilities.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. In the 4. quarter of 2019 and in the 1., 2., 3. and 4. quarter of 2020 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
94) Protection against noise, protection of the atmosphere / The whole sections of the embankment	Whenever possible the works should be carried out section by section, i.e. after completing works in a given section and its reclamation, works should begin at the next embankment section intended for extension.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
95) Water and soil protection / The whole sections of the embankment	During construction works, the soil-water environment should be protected against contamination with substances used, sewage, or waste generated in connection with executed works. Grease and fuel to be stored at adequately prepared place with relevant sealing degree and equipped with sorbent to neutralize petroleum substance. In the event of spillage of oil derivative substances, it must be promptly removed and contaminated soil layers must be immediately eliminated (by a specialized company) and managed in accordance with applicable law. Such places must be brought back to their initial condition. In the event of oil derivative substance spillage to surface water, the Contractor is obliged to ensure mechanical collection of the substance from the water surface and its neutralization or disposal.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. From the 2. quarter of 2020 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
96) General principles for carrying out works / The whole sections of the embankment	The Contractor should choose a place for storing topsoil which will secure it against pollution, being driven through and being tamped down.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. In each quarter problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
97) General principles for carrying out works / The whole sections of the embankment	Topsoil should be stored and protected in a way enabling its re-use.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. In each quarter problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
98) Environmental protection / The whole sections of the embankment	For works performance, it is necessary to use only non-hazardous materials which are not burdensome to the environment.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
99) Fauna protection / The whole sections of the embankment	No substance which could be lethal to animals can be used for execution of works (excluding substances necessary for proper operation of construction machines).	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
100) General principles for carrying out works / The whole sections of the embankment	Earthworks shall be carried out so that no damage is caused to regulatory structures. The Contractor shall ensure the patency of embankment culverts throughout the duration of the works.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
101) Archaeological supervision / The whole sections of the embankment	Contractor is obliged to ensure permanent archaeological supervision during of earthworks.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period
(1)	(2)	(3)
102) Archaeological findings / The whole sections of the embankment	In the case of discovery of immovable structures or mobile archaeological monuments the Contractor is obliged to notify immediately the Podkarpacki Heritage Conservator as well as the Employer and the Engineer. During Works' implementation the Works Contractor shall comply with guidelines of the Heritage Conservator. Vide: a letter from the Voivodship Office for the Heritage Conservation, sign: UOZ-T-1.5183.69.2016 dated 16.11.2016.	NOT APPLICABLE There was no need to implement the measure in the reporting period (no immovable structures or mobile archaeological monuments referred to in item 102 of the Appendix 1 to EMP were found).
103) Unexploded ordinances / The whole sections of the embankment	Contractor is obliged to ensure permanent sapper supervision during of earthworks regarding checking and cleaning the area from unexploded ordinances.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
104) Health and Safety / The whole sections of the embankment	HIV-AIDS Prevention. The Contractor shall conduct an HIV-AIDS awareness programme and shall undertake such other measures to reduce the risk of the transfer of the HIV virus between and among the Contractor's Personnel and the local community, to promote early diagnosis and to assist affected individuals.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
105) Soil and water protection / The whole sections of the embankment	It is necessary to provide training to all the employees with regard to: - maintaining appropriate hygienic conditions within the area of the construction site and its direct surrounding; - prohibition of penetrating the "Wisła pod Zawichostem" Nature Reserve as well as other enclosed natural habitats; - prohibition of the burning of open fire both inside the construction site and its surrounding, this is understood as the fires, the burning of waste or branches from the cutting trees or shrubs. Appropriate penalties for noncompliance with these rules should be included in the Contractor's work regulations.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.
106) Soils, surface water and air protection / The whole sections of the embankment	The type and working order of such equipment must ensure the protection of soil, surface waters and ground waters against pollution, dust and gas emission to the air and noise emission.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. From the 2. quarter of 2020 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.
107) Air protection (Protection against dusting) / The whole sections of the embankment	Limit dust generation, in dry periods, caused by the means of transport among others by: using tarpaulins when transporting aggregate and bulk materials, cleaning vehicle wheels before entering the public roads, cleaning technological internal roads surface, prevention of contamination of local roads with sand and other material transported by vehicles.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. In the 3. and 4. quarter of 2019 and in the 1., 2., 3. and 4. quarter of 2020 problems were found in the implementation of the measure as described in section 5.1.4 of the Report.

Item	Mitigation measure according to Appendix 1 to EMP	Status of the measure completion in the reporting period		
(1)	(2)	(3)		
	Bulk materials and construction aggregate for use in the construction phase should be protect against the blowing and excessive dusting from the surface both during storage and during incorporation (particularly in the vicinity of agricultural crops and built-up areas) e.g. by using tarpaulins or sprinkling of ground surfaces during rain-free periods.			
Air protection (Protection against dusting) / Embankment sections where cutoff walls will be made	It is necessary to apply required measures limiting dust emission at the time of construction of the cut-off wall using Deep Soil Mixing technology.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was completed in the 3. quarter of 2019. No problems were found in the implementation of the measure.		
109) Environment, human health and safety protection	The Contractor and Contractor's environmental team is responsible for training of the rules and conditions of the EMP for Contractor's management and engineering-technical personnel.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.		
110) Periodic meetings environmental team	During the implementation of the tasks arising from the EMP monthly team meetings of PIO, Consultant and Contractor will take place to discuss and monitor the implementation of mitigating and monitoring measures.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.		
There will be monthly reports prepared by the Contractor which will cover measures conducted under the Contractor's environmental supervision; both in Polish and in English, in paper and electronic versions with reference to the obligations required by EMP and other contractual documents. These documents will be subject to the approval of the Engineer and the Employer. The whole sections of the embankment The whole sections of the embankment The whole sections of the embankment The contractor will be contained documents confirming the participation of specialists (e.g. memorandum of understanding and/or a declaration of a specialist confirming the proper performance of measures) together with photographic documentation. The Contractor will also prepare a commencement report, ad-hoc reports (as needed) and a closure report.		COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.		
H) - REQUIREMENTS AFTER COMPLETION OF THE WORKS				
Soil protection, flora protection / The whole sections of the embankment	Upon the completion of earthworks, it is necessary to immediately clean up the area covered by these works: sow any damaged ground surfaces, grass the redeveloped section of the embankment and sow with a mixture of indigenous plants conforming habitat requirements in order to minimize surface erosion and suspension-forming fractions fail to reach waters.	COMPLETED The implementation of the measure started in the 3. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.		

Item Mitigation measure according to Appendix 1 to EMP		Status of the measure completion in the reporting period		
(1)	(2)	(3)		
113) Recommended environmentally friendly technical solutions	It is necessary to make plantings upon the completion of works within the reinforcements. In order to strengthen the area of these plantings, jute meshes are recommended to protect crops and seedlings exposed to water erosion. Plantings should be made taking into account the following conditions: a) use plants from the same catchment area for planting aquatic plants, b) use local seeding material or/and grass fragments (obtained prior to the start of works) for seeding lands being exposed during works, c) use self-seedlings (preserved in the course of preparatory works) as much as possible in order to make woodlots.	NOT APPLICABLE There was no need to implement the measure in the reporting period (no need to make reinforcements (not included in the project) referred to in item 113 of the Appendix 1 to EMP were found).		
114) Contractor's environmental supervision team / The whole sections of the embankment	Report containing information concerning the method and scope of the performance of mitigation measures, and also documents confirming the participation of specialists (e.g. memorandum of understanding and/or a declaration of a specialist confirming the proper performance of measures together with photographic documentation) should be prepared by the Contractor within 6 months from the date of works completion. Upon approval of the report by the Engineer and RZGW the report will be submitted to the Regional Director for Environmental Protection in Rzeszów.	NOT APPLICABLE There was no need to implement the measure in the reporting period (the measure referred to in item 114 of the Appendix 1 to EMP did not concern the works implementation period).		
115) General principles of nature protection - prevention and elimination of invasive species / The whole sections of the embankment	For a minimum period of 5 years from the completion of construction works the area covered by the project should be monitored for the occurrence of invasive foreign plants. In case such species are found, it is required to take actions to remove them. This monitoring should be run while the embankments are mowed. In case such conducted treatments referring to the embankments and their maintenance (e.g. mowing) are not effective to remove the above-specified plants, the Contractor's botanical supervision which supervises the area will specify measures aimed to eliminate the above specified species should cover the expanded embankments but also the area which is adjacent to them which is not less than the one located within the project demarcation lines. Based on such botanical monitoring and its results the Investor will take appropriate action to eliminate these plants.	NOT APPLICABLE There was no need to implement the measure in the reporting period (the measure referred to in item 115 of the Appendix 1 to EMP did not concern the works implementation period).		
116) Land area and landscape protection / All work areas	Places sowed with grass mixes should be taken care of by means of, among others, twofold mowing of flood embankments during the year and removal of hard lichens. This activity includes period of construction works realization and also the Defect Notification Period and Warranty Period. Rules of mowing are indicated below in item 116.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.		
117) Land area and landscape protection / All work areas	The embankment at the operation stage will be mowed: a) within Section I - mowing at the embankment water-side slope will start not earlier than on 15 June, then at the embankment water-side slope - not earlier than on 1 July,	COMPLETED The implementation of the measure started and was completed in the 4. quarter of 2020. No problems were found in the implementation of the measure.		

Itom	Item Mitigation measure according to Appendix 1 Status of the measure completion in the				
rtem	to EMP	reporting period			
(1)	(2)	(3)			
	b) within Section II, II and Section San River - mowing will start not earlier than 1 June, c) the embankment should be mowed in turns i.e. on 1 June the embankment will be mowed along a length of, for example, 300 meters, then further 300-metre sections will be mowed with a delay two weeks; in case of necessity (to remove invasive vegetation) it is acceptable to mow the embankment at an earlier date, in consultation with the Contractor's environmental supervision team.				
Buildings protection / The whole sections of the embankment with building	After completion of the works, the Contractor will carry out an inventory of the existing buildings and structures. Losses or damages resulting from the works execution by the Contractor shall be borne by the Contractor.	COMPLETED The implementation of the measure started and was completed in the 4. quarter of 2020. No problems were found in the implementation of the measure.			
After completing all construction works, areas temporarily occupied for access roads, facility and storage yards should be restored to their prior condition.		COMPLETED The implementation of the measure started in the 3. quarter of 2020 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.			
I) - GENERAL REQUIREMENTS					
120) Legislation in the country where the Agreement is to be implemented / All work areas	Contractor is obliged to knowledge and adherence to all laws currently binding in the country where the Agreement is to be implemented in the period of construction and assembly works and the Defects Notification Period and the Warranty Period. None of the provisions above do not exempt the Contractor from the application of the law.	COMPLETED The implementation of the measure started in the 2. quarter of 2019 and was carried out until the end of the reporting period. No problems were found in the implementation of the measure.			

developed by: Rafał Salach
signature:
place and date: Rzeszów:
verified by: Marcin Moczulski
signature:
place and date: Rzeszów:
approved by: Adrianna Siemionek - Ryszkowska
signature:
place and date: Rzeszów:

	of measures listed in Appendices 1 and 2 to the EMP for the Contract 3B.2
Reporting period: 04/01/2019 -	- 12/25/2020

Part II. Checking list on implementation of monitoring measures listed in Appendix 2 to the EMP for the Contract 3B.2

Explanations to Check List presented in Part II

Measures listed in Appendix 2 to the EMP for the Contract 3B.2 are divided into 9 categories (marked with letters A - I) and described in checking lists (IN CAPITAL ITALIC FONT):

Sign	Category	Item
A-I)	Monitoring of the implementation of mitigating measures from Appendix 1 to the EMP	Items. 1-120

The numbers in column "Item" – from l) to l20) – represent the numbers of particular monitoring measures, in accordance with the numbers from Appendix 2 to the EMP.

For each of the monitoring measures, the following was given:

- brief description of the measure (marked in *bold italic font*, together with a number in the "Item" column);
- exact description of the measure in the text of Appendix 2 to the EMP (along with guidelines for the implementation of a given monitoring measure, provided in Appendix 2 to the EMP);
- description of the implementation status of the measure in the reporting period.

Table 2. Checklist for the implementation of monitoring measures listed in Appendix 2 to the EMP for the Contract 3B.2

Item	Monitoring measure according to Appendix 2 to the EMP	Implementation status in the reporting period	
(1)	(2)	(3)	
A) – I) MONITORING OF THE IMPLEMENTATION OF MITIGATION MEASURES FROM APPENDIX 1			
1-120)	Monitoring of the implementation of mitigation measures from Appendix 1 to the EMP Monitoring of the implementation of mitigation measures listed in items 1-120 in Appendix 1 to the EMP. Detailed guidelines for implementation of abovementioned measure listed in items. 1-120 of the Appendix 2 to the EMP: The subject of monitoring According to the descriptions provided in items 1-120 in Appendix 2 of the EMP. Location of monitoring According to the descriptions provided in items 1-120 in Appendix 2 of the EMP. Method of monitoring According to the descriptions provided in items 1-120 in Appendix 2 of the EMP. Method of monitoring According to the descriptions provided in items 1-120 in Appendix 2 of the EMP. Time and frequency of monitoring According to the descriptions provided in items 1-120 in Appendix 2 of the EMP. Monitoring Unit	COMPLETED The implementation of the measure started in the second quarter of 2019 and conducted until the end of the reporting period. No problems were found in the implementation of the measures.	
	Investor, Engineer and Contractor (according to descriptions provided in items 1-120 of the Appendix 2 to the EMP).		

developed by: Rafał Salach
signature:
place and date: Rzeszów:
verified by: Marcin Moczulski
signature:
place and date: Rzeszów:
approved by: Adrianna Siemionek - Ryszkowska
signature:
place and date: Rzeszów:

Part III. List of quantitative summary of the implementation of measures listed in Appendices 1 and 2 to the EMP during the reporting period

The table below presents a quantitative summary of the implementation of measures listed in Appendices 1 and 2 of the Environmental Management Plan (EMP) for the Contract 3B.2 in the reporting period.

Category		Mitigation measures (items 1-120* in Appendix 1 to the EMP)		Monitoring measures (item 1-120* in Appendix 2 to the EMP)	
	Count	Item No.	Count	Item No.	
Measures implemented and completed during the reporting period	115	items 1-59, 61-101, 103-112, 116-120	120	items 1-120	
Measures not implemented during the reporting period (recognized as not applicable to the reporting period - there was no need to implement those measures))	5	items 60, 102, 113-115	0	items –	

^{*} in the case of measures under item 28, 115 and 117 in Appendix 1, their implementation during the Defect Notification Period and the Warranty Period is assigned to the Contractor. After the end of the Defect Notification Period and the Warranty Period, the above-mentioned measures are assigned to a designated organizational unit of OVFMP.