

APPENDIX NO. 2
Photographic documentation of selected EMP activities
implemented during of Contract execution



November 2017, Chlewice, removal of humus prior to the commencement of works



January 2019, Chlevice, flood embankment prior commencement of topsoiling



December 2020, Chlevice, flood embankment prepared for sowing grasses



May 2021, Chlevice, a pair of storks preparing for the hatching



August 2021, Chlewice, greening of embankments



September 2017, Marwice - Krajnik, condition of embankments before the modernization



April 2021, Marwice - Krajnik, raising the embankment crown



November 2021, Marwice - Krajnik, grass growth on the embankment and reclaimed area of the previously existing construction site (on the right side of the road)



October 2017, Gryfino-Mniszki, initial scope of works



April 2021, Gryfino-Mniszki, constructed cut-off wall



October 2021, Gryfino-Mniszki, embankment structure prepared for topsoiling



October 2021, Gryfino-Mniszki, completed embankment section