

APPENDIX No. 2

Photo documentation for 2A.1/2 Contract



Photo.1. Marked and secured patch of naturally valuable area nearby the performed construction works.



Photo.2. New stream bed of Nowinka, slopes of the stream have been topsoiled and seeded with a mixture of grasses - Contract implementation stage.



Photo.3. Newly-built section of the 3233D county road. Plantings of trees can be seen along the road - Contract implementation stage.



Photo.4. One of the compensatory areas in the investment premises. The area has been fenced and prepared for nature compensations - Contract implementation stage.



Photo.5. Layout of the Goworówka stream bed in the gallery under the reservoir dam - Contract implementation stage.



Photo.6. OSH spot located in the site facilities - Contract implementation stage.



Photo.7. Reservoir basin - visible growth of mixture of grasses (Defects Notification Period).



Photo.8. Bat box installed on the tree at the investment premises - Contract implementation stage.



Photo.9. Dipper box installed in the investment premises under the new bridge over Nowinka stream - Contract implementation stage.



Photo.10. Works execution for 2A.1/2 Contract – March 2021.



Photo.11. The flood control reservoir from the west side; operation stage (Defects Notification Period)
- May 2022.