Appendix no. 2 Photographic documentation of selected EMP measures implemented during the implementation of the Contract



November 2021, Piasek, preparation of construction facilities with flood protection



February 2022, Piasek, humus collection in the area designated for the embankment







Final Report on implementation of the measures specified in Environmental Management Plan for Contract 1A.2



February 2022, Krajnik, execution of works related to laying the cable outside the period of Aquatic Warbler activity



April 2022, Piasek, humus storage site marking







Final Report on implementation of the measures specified in Environmental Management Plan for Contract 1A.2



May 2022, Krajnik, completion of works related to laying the cable outside the period of activity of the Aquatic Warbler



April 2022, Gryfino, information campaign on infectious diseases









August 2022, Gryfino, construction site signage



August 2022, Piasek, replacement plantings agreed with the Cedynia municipality









October 2022, Piasek, reptile and amphibian barriers



April 2023, Gryfino, reclamation of the place of temporary occupation and replacement planting








Final Report on implementation of the measures specified in Environmental Management Plan for Contract 1A.2



July 2023, Krajnik, one of the nests installed for martins



July 2023, Piasek, maintenance work on grassy surfaces - mowing





