

**Photo documentation
for Contract 1B.5/3**

Appendix 2 to the Final Report

This document constitutes Appendix No. 2 to the Final Report on the implementation of measures specified in the Environmental Management Plan for Contract 1B.5/3

(reporting period: July 2021 – November 2023)



Photo 1. Track in the central part of the Task prior to the start of works.



Photo 2. Tree and shrub felling in the Task area.



Photo 3. Protection for trees at risk of damage.



Photo 4. Containers for waste sorting.



Photo 5. Protected habitats: riparian willow forest and oxbow lake in the vicinity of the Task area.



Photo 6. Fencing and marking of protected habitats with signs, installation of nesting boxes.



Photo 7. Herpetological fencing at a body of water.



Photo 8. Excavations – potential traps for small animals.



Photo 9. Site of the invasive species of Sakhalin knotweed on a railway embankment.



Photo 10. Bridge over Suchodół – an object included in the provincial records of monuments.



Photo 11. Inspection of the condition of access roads.



Photo 12. Railway embankment – land reclamation.



Photo 13. Reclaimed area of the main site facilities.



Photo 14. Reclaimed area of the storage yard.