

Appendix no. 6 to the Final Report on Implementation of the Land Acquisition and Resettlement Action Plan (LARAP) for Contract 3D.2/1 *Construction of the right embankment of the Biala River in the City of Tarnów*



Photo. 1. Condition of the Construction Site before the start of works implementation – allotment gardens at FAG SEMAFOR.



Photo. 2. Condition of the Construction Site before the start of works implementation – allotment gardens at FAG SEMAFOR.



Photo. 3. Condition of the Construction Site before the start of works implementation – allotment gardens at FAG SEMAFOR.



Photo. 4. Condition of the Construction Site before the start of works implementation – allotment gardens at FAG SEMAFOR.



Photo. 5. Condition of the Construction Site before the start of works implementation – allotment gardens at FAG SEMAFOR.



Photo. 6. Condition of the Construction Site before the start of works implementation – allotment gardens at FAG SEMAFOR.



Photo. 7. Condition of the Construction Site before the start of works implementation – allotment gardens at FAG SEMAFOR.



Photo. 8. Condition of the Construction Site before the start of works implementation – allotment gardens at FAG SEMAFOR.



Photo. 9. Removal of trees in the embanked area of the Biala River.



Photo. 10. Tidying-up of the area after removal of trees.



Photo. 11. Embanked area after tidying-up.



Photo. 12. Zone of demolition works of building structures in area of allotment gardens, 2nd decade of November 2020.



Photo. 13. Zone of demolition works of building structures in area of allotment gardens, 2nd decade of November 2020.



Photo. 14. Construction of embankment, 2nd decade of December 2020.



Photo. 15. Fencing off the zone of allotment gardens from the belt of works, 2nd decade of December 2020.



Photo. 16. View of excavation fencing, 3rd decade of July 2021.



Photo. 17. Zone of works and excavation for storm sewer, 3rd decade of July 2021.



Photo. 18. Construction of embankment, 2nd decade of August 2021.



Photo. 19. Excavation area for the storm sewer, 3rd decade of August 2021.



Photo. 20. Excavation for anti-filtering shield, 2nd decade of September 2021.



Photo. 21. New embankment of the Biała River after completion of construction. Connection to the railway embankment.



Photo. 22. New embankment of the Biała River after completion of construction. Visible fence of FAG SEMAFOR made as part of the Contract.



Photo. 23. New embankment of the Biała River after completion of construction.



Photo. 24. New embankment of the Biała River after completion of construction.



Photo. 25. New embankment of the Biała River after completion of construction.